



WHEEL BEARING
RANGE

DIAGNOSTIC EXPERT

ANALYSIS & RECOMMENDATIONS

NTN **SNR**

www.ntn-snr.com



With You



MAIN CAUSES OF FAILURE

Most failures are detected by **noise**; however, there are many causes

- 1 Indentations or breakage of the shoulder
- 2 Scratches on successive balls
- 3 Consecutive flaking due to a faulty seal
- 4 Fatigue spalling
- 5 Seizure / Overheating / Faulty lubrication
- 6 Loss of grease
- 7 Vibration
- 8 Difficulty in steering straight
- 9 Clacking / Noise
- 10 ABS faults

In most of the cases, when one of these faults occurs, there is no alternative other than to replace the bearing.



GENERAL RECOMMENDATIONS RELATED TO FITTING

- Use the correct tools
- Work in a clean and clear area and avoid dropping the part
- An assembly with an abnormal noise requires the bearing to be changed
- Never loosen or tighten the driveshaft nut when vehicle is on the floor
- Do not let the vehicle down on the floor with the driveshaft loose or removed
- The surface of hub and driveshaft must be checked for damage (no cracks or deep scratches)
- To ensure correct operation of the wheel speed sensor, make sure the magnetic seal does not remain in contact with any magnetic part
- Bearings should always be handled with care in order to avoid any damage
- Comply with the manufacturer's torque recommendations



1

INDENTATIONS OR BREAKAGE OF THE SHOULDER DUE TO A FAULTY FITTING

EVIDENCE

- Presence of indentations located on the edge of the track and often seen over the complete circumference of the ring
- The indentations are in line with the position of the rolling elements
- Damaged or broken shoulder
- A slapping noise to the assembly

CAUSES

- The bearing was off-centre when fitted
- The bearing fitting was incorrect
- The bearing was dropped onto a hard surface
- The bearing tightening load was transferred through the rolling elements



NTN-SNR ADVICE

- Apply the load on the right ring, the fitting force should not go through the rolling elements
- Follow the general recommendations related to fitting



2

SCRATCHES ON SUCCESSIVE BALLS FROM AN UNTIGHTENED DRIVESHAFT

EVIDENCE

- Damage with circular grooves deforming the surface of the balls
- Grooved scratches similar to "petanque balls"
- Matching damage on the bearing tracks

CAUSES

- The vehicle was moved without the driveshaft or hub nut in place (such as when being serviced)
- Damage on the balls from contact and rolling on the inner edge of the track, due to a gap between the inner races



NTN-SNR ADVICE

- Avoid moving any vehicle when the driveshaft nut is not tight



3

CONSECUTIVE FLAKING DUE TO A FAULTY SEAL

EVIDENCE

- Local or generalised oxidation of the bearing
- Reddish or black staining more or less widely distributed on the bearing
- Pitting has damaged the surface to a variable extent

CAUSES

- Insufficient or incorrect sealing for the installation
- Damage to the bearing seal during maintenance
- Lack/non replacement of the cap



NTN-SNR ADVICE

- Never dis-assemble a sealed bearing, damage is inevitable
- Avoid spraying with liquids
- Follow the general recommendations related to fitting



4 FATIGUE SPALLING

EVIDENCE

- Track surface damaged from flaking

CAUSES

- Faulty fitting
- Faulty (deformed) mating components



NTN-SNR ADVICE

- Follow the general recommendations related to fitting



5

SEIZURE / OVERHEATING / FAULTY LUBRICATION

EVIDENCE

- The bearing has shallow metal surface damage on the tracks
- The bearing components are welded
- Components are coloured

CAUSES

- Lack of or incorrect bearing lubrication
- Micro-welding between bearing components
- Grease is contaminated due to pollution ingress



NTN-SNR ADVICE

- Watch out for any possible loss of grease which appears unusual
- Follow the general recommendations related to fitting



6 LOSS OF GREASE

EVIDENCE

- The mechanic notes an escape of grease from the bearing seals

CAUSES

- A large rise in bearing temperature causing deterioration of the grease
- Entry of water contaminates the grease

NTN-SNR ADVICE

- Check that there is not an overheating problem (e.g. a sticking hand brake)
- Check the bearing seal condition





7 VIBRATION

EVIDENCE

- On the road, the driver senses vibrations in the driving compartment

CAUSES

- Bad condition of the mating parts (a balance problem)
- Incorrect tightening of the bearing



NTN-SNR ADVICE

- Check the wheel balance
- Follow the general recommendations related to fitting of the wheel bearing or torque



8

DIFFICULTY IN STEERING STRAIGHT

EVIDENCE

- Driven in a straight line the vehicle tends to drift to the left or to the right

CAUSES

- Incorrect adjustment of the drivetrain
- Steering system stiffness: worn ball joints
- Incorrect tightening of the bearing

NTN-SNR ADVICE

- Check the axle adjustments
- Replace the ball joints





9

CLACKING / NOISE

EVIDENCE

- A loud noise from the front axle (when parking)

CAUSES

- A small movement of the bearing in the stub axle housing

NTN-SNR ADVICE

- Check the dimensions and condition of the stub axle housing





10 ABS FAULTS

EVIDENCE

- The ABS warning panel light comes on or remains on

CAUSES

- Computer failure
- Sensor failure
- Connection problem
- Encoder deteriorated
- Bearing fitted the wrong way round



NTN-SNR ADVICE

- Check the encoder and sensor are clean
- Never bring a magnet near to the encoder
- To fit bearings of first generation in the right way, make sure to use the ASB® test card
- Use of the NTN-SNR card tester is essential



