



TIMING AND ACCESSORY Ranges

Diagnostic Expert **Analysis & Recommendations**



MAJOR CAUSES OF TIMING BELT FAILURES:

- 1 Uneven breakage
- 2 A clean break
- 3 Detached or separation of the belt teeth
- 4 Ripped teeth
- 5 Split teeth
- 6 Loss of teeth and material
- 7 Worn belt
- 8 The back of the belt is split
- 9 Wear on the edge
- 10 Molten belt
- 11 Automatic tensioners
- 12 Overheated roller
- 13 Mounting bracket broken (or reduced operating clearance)
- 14 Broken screw
- 15 The roller is not positioned correctly
- 16 Seizure and / or unusual noise
- 17 Corrosion of the track
- 18 Damaged mounting bracket
- 19 Oil leaks
- 20 Misalignment and early failure of the actuator
- 21 Damaged seal
- 22 Unusual vibration from the roller arm



GENERAL RECOMMENDATIONS

- ☐ Do not store the belts in sunlight
- ☐ Never fold, turn or twist a belt
- ☐ Do not force the belt onto pulleys
- ☐ Always use the correct tools when fitting belts
- ☐ Follow the recommended tension (use specific tools, for tensioners, direction of roller tension, and rotation of engine)
- ☐ Pay strict attention to the manufacturers' specifications and specialist documents on applications and their wear
- ☐ Tighten fastening screws, paying attention to the published tightening torque
- ☐ Check the condition of all mating components in the belt path (rollers, pumps and pulleys)
- ☐ Check the condition of the casings and remove all un-used parts
- ☐ In all cases a belt change is needed, we can not re-use a belt



1 UNEVEN BREAKAGE

EVIDENCE

- The belt is torn diagonally

PROBABLE CAUSES

- Over tightened belt
- Jammed by another part
- Contamination solid or liquid

NTN-SNR ADVICE

- Observe the general recommendations relating to the assembly



use visual inspection e.g.
to check for wear





2 A CLEAN BREAK

EVIDENCE

- The belt is ripped apart

PROBABLE CAUSES

- Defective material
- Use of unsuitable tools
- The belt was twisted
- Contamination solid or liquid

NTN-SNR ADVICE

- Observe the general recommendations relating to the assembly





3 DETACHED OR SEPARATION OF THE BELT TEETH

EVIDENCE


- Detached or separation of the belt teeth

PROBABLE CAUSES

- Low belt tension – loss of tension
- An obstruction by an unknown component
- Contamination solid or liquid
- Incorrect tools used during fitting

NTN-SNR ADVICE

- Check the mounting of the tensioner
- Eliminate any leakages
- Observe the general recommendations relating to the assembly





4 RIPPED TEETH

EVIDENCE

- Loss of teeth

PROBABLE CAUSES

- Complete or partial hardening of a timing component

NTN-SNR ADVICE

- Do not install the belt on seized parts or those with excessive play
- Observe the general recommendations relating to the assembly





5 SPLIT TEETH

EVIDENCE

- Splits at the base of the teeth

PROBABLE CAUSES

- Belt is under tensioned
- An obstruction by an unknown component
- Incorrect tools used during fitting



NTN-SNR ADVICE

- Observe the general recommendations relating to the assembly



6 LOSS OF TEETH AND MATERIAL

EVIDENCE

- The teeth have detached themselves from the fabric of the belt

PROBABLE CAUSES

- Low belt tension - loss of tension
- An obstruction by an unknown component
- Contamination by liquid

NTN-SNR ADVICE

- Eliminate leaks
- Observe the general recommendations relating to the assembly





7 WORN BELT

EVIDENCE

- Internal structure of the belt is visible

PROBABLE CAUSES

- Belt tension too tight
- Worn pulleys
- Operating temperature is too high

NTN-SNR ADVICE

- Observe the general recommendations relating to the assembly
- Check the engine is cool
- Check and replace worn pulleys





8 THE BACK OF THE BELT IS SPLIT

EVIDENCE

- Cracks on the back of the belt

PROBABLE CAUSES

- Temperature too low or too high
- Ageing of the belt
- Contact with an unknown component



NTN-SNR ADVICE

- Check if other parts are overheating
- Replace the belt
- Check the condition of the housing
- Check the engine is cool



9 WEAR ON THE EDGE

EVIDENCE

- Reduction in belt width
- One-sided wear of belt

PROBABLE CAUSES

- Misalignment of pulleys /or tensioner
- Contact with an unknown part

NTN-SNR ADVICE

- Replace the belt
- Observe the general recommendations relating to the assembly





10 MOLTEN BELT

EVIDENCE

- The internal structure of the belt is revealed on the back

PROBABLE CAUSES

- Excessive tension
- Obstruction by external parts

NTN-SNR ADVICE

- Change the blocked items
- Observe the general recommendations relating to the assembly





11 AUTOMATIC TENSIONERS

EVIDENCE

- Under tightened =
Lower stop marked or broken
- Over tightened =
Upper stop marked or broken

PROBABLE CAUSES

- Incorrect tension

NTN-SNR ADVICE

- Observe the general recommendations relating to the assembly



Lower stop
marked or broken



Upper stop
marked or broken



12 OVERHEATED ROLLER

EVIDENCE

- The roller is disassembled and miscoloured

PROBABLE CAUSES

- Excessive tension
- Obstruction by external parts (heat has spread from the back of the belt)

NTN-SNR ADVICE

- Observe the general recommendations relating to the assembly





13 MOUNTING BRACKET BROKEN (OR REDUCED OPERATING CLEARANCE)

EVIDENCE

- Broken centre of the roller

PROBABLE CAUSES

- Lubricated screw
- Over tightening that has caused a breakage of the support surface



NTN-SNR ADVICE

- Observe the general recommendations relating to the assembly



14 **BROKEN SCREW**

EVIDENCE

- The screw has split apart

PROBABLE CAUSES

- Lack of tightening
- Metal fatigue of the screw from back and forth movement of the roller.
The screw was subject to shear stresses



NTN-SNR ADVICE

- Tighten the screws to the exact recommended torque
- Lubricate the unthreaded shank of the screw but not the threads



15 THE ROLLER IS NOT POSITIONED CORRECTLY

EVIDENCE

- Tensioner indexing is not correct
- Circular marking
- Purple discolouration
- Seizure of the roller and friction on the belt

PROBABLE CAUSES

- Incorrect tension, bad index position on the engine housing
- Crushed roller plate by contact from centering on the engine



NTN-SNR ADVICE

- Change the belt
- Observe the general recommendations relating to the assembly



16 SEIZURE AND / OR UNUSUAL NOISE

EVIDENCE

- Extensive corrosion

PROBABLE CAUSES

- Omission of the protection cap when fitting, allowing water and dust to enter the bearing
- The grease is degraded by the contamination and cannot correctly lubricate the internal elements

NTN-SNR ADVICE

- Always fit the cap provided for the roller
- Check the correct position of deflectors





17 CORROSION OF THE TRACK

EVIDENCE

- Significant deposits of pollution

PROBABLE CAUSES

- The grease is degraded by the contamination and cannot correctly lubricate the internal elements

NTN-SNR ADVICE

- Avoid using high pressure washers on the engine
- Check the correct installation of deflectors and engine casings





18 DAMAGED MOUNTING BRACKET

EVIDENCE

- Distortion or absence of the mounting arm

PROBABLE CAUSES

- Incorrect tightening or loosening of the joint

NTN-SNR ADVICE

- Tighten the screw to the recommended torque
- Lubricate the unthreaded shank of the screw but not the threads





19 OIL LEAKS

EVIDENCE

- Leaks from the actuator

PROBABLE CAUSES

- Mishandling /shocks when fitting the part
- Using an unspecified actuator

NTN-SNR ADVICE

- Use the correct length of belt
- Observe the general recommendations relating to the assembly





20 MISALIGNMENT AND FAILURE OF THE ACTUATOR

EVIDENCE

- Damaged actuator

PROBABLE CAUSES

- Washer not fitted during fitting, leading to misalignment of the actuator and early failure
- Under or over tightening of the joint

NTN-SNR ADVICE

- Do not forget to refit the washer





21 DAMAGED SEAL

EVIDENCE

- Seal on the roller is damaged

PROBABLE CAUSES

- Mishandling /shocks when fitting the part

NTN-SNR ADVICE

- Fit all parts supplied with the roller
- Replace the damaged roller with a brand new roller



22 UNUSUAL VIBRATION FROM THE ROLLER ARM

EVIDENCE

- Spring broken
- Premature wear of the roller

PROBABLE CAUSES

- Length of the belt is incorrect
- Obstruction by external parts

- Check and replace as required, the free wheel pulley and the alternator pulley damper







NTN-SNR Roulements - Rue des usines - 74000 Annecy - France
RCS ANNECY B325 821 072 - Code APE 2815Z - Code NACE 28.15

www.ntn-snr.com