



# CVJ BOOTS

## Possible causes of damage


### Damage

- Grease leakage
- Presence of grease under the clamp



- 1- Bad clamping
- 2- Bad clamp or bad boot position

### 3- Tear Boot



- 4- Shock on the boot clamp

## - Boot reversion



Causes :

- 1- Bad handling
- 2- External damage / aggression
- 3- Strong pressure on the boot

## - Cutting



Causes :

- 1- External impact / shock
- 2- Damage / aggression
- 3- Tightening clamp too important

## Recommendations

The manufacturers fitting instructions and specified torque setting should always be followed. The correct tools should always be used for the removal and fitment process.

Refer to the vehicle applications in our online catalogue: [e-shop](#)



Scan this QR code to access our online catalogue.

**ALWAYS FOLLOW THE VEHICLE MANUFACTURERS FITTING RECOMMENDATIONS**

© NTN-SNR ROULEMENTS

The contents of this document are the copyright of the publisher and any reproduction, even partial, is prohibited without permission. Despite the care taken in preparing this document, NTN-SNR Roulements disclaims any liability for errors or omissions that may slip through, as well as for losses or direct or indirect damage arising from its use.

