



Brand of NTN corporation



## Drive shaft and CVJ ranges dedicated to light commercial vehicles

Give commercial vehicles all the quality benefits of SNR products:

- to reduce their downtime, thereby saving time and money,
- to reduce accident rates for LCV drivers,
- to enable vehicles to carry large loads without compromising performance.

**75** LCV-specific part numbers

- **35** complete drive shafts (DK)
- **19** CVJ kits (OJK)
- **21** boot kits (OBK: wheel side) (IBK: differential side)

Covers **60%** of LCV applications throughout Europe

### Typical applications

**Renault** Master, Trafic • **Peugeot** Expert, Boxer  
**Citroën** Jumpy, Jumper • **Mercedes** Vito, Viano  
**Fiat** Ducato, Scudo • **Opel** Movano, Vivaro, Combo  
**Volkswagen** Transporter • **Nissan** NV400, Interstar



*Trucks travel millions of kilometres each year. Operators shoulder heavy constraints and challenges such as annual maintenance costs, fleet downtime, fuel consumption and European standards. They demand reliable, high-performance products to ensure optimum efficiency. And that's what we offer them with our drive shaft/CVJ aftermarket range. »*

**Romain Petellaz,**  
Product Line Manager, CVJ range



# Find all our product information and applications on TecDoc



| Reference  |  | Vehicle applications  | OE numbers   |
|--|--|---|--|
| <b>DK53.016</b>  | Front left   | Nissan NV400 9/2011 => 6/2014   | 3910100Q4K, 3910100Q4F, 3910100Q4E, 3910100Q3G   |
| <b>DK68.023</b>  | Front right  | Nissan NV400 FL 6/2014 =><br>Nissan NV400 Autocar 11/2011 => 9/2016<br>Renault Master III 4/2010 => 6/2014<br>Renault Master III FL 5/2014 =><br>Opel Movano B 5/2010 => 5/2015<br>Opel Movano B FL 5/2015 => 7/2019  | 95516047, 95514705, 95513818, 93167851, 4422058, 4420055, 4406518, 4406234<br>391016979R, 391012675R, 301012675R, 391012849R, 391012360R, 8200842365<br>3910000Q5B, 3910000Q4H, 3910000Q3M, 3910000Q4G<br>95516046, 95514706, 95513819, 93167650, 4422057, 4420054, 4406519, 4406235<br>391005187R, 391009620R, 391004255R, 8200842369 |
| <b>DK53.021</b>  | Front left   | Renault Master II 9/1997 => 9/2003<br>Renault Master II phase 2 10/2003 => 1/2011   | 8200178618, 8200485576, 8200052428, 9109720, 4401720   |
| <b>DK55.262</b>  | Front right  | Opel Movano A 10/1998 => 9/2003<br>Opel Movano A FL 10/2003 => 10/2006<br>Opel Movano A FL 2 10/2006 => 10/2010   | 7700102999, 8200169281, 7711135279, 7711135280, 8200052426, 7700102980<br>4401191, 4417358   |
| <b>DK53.020</b>  | Front right  |   | 8200499895, 8200169288   |
| <b>DK55.263</b>  | Front left   | Opel Vivaro A 5/2001 => 7/2006<br>Opel Vivaro A FL 7/2006 => 10/2014  | 391018828R, 8200179212, 7711135189, 8200334338, 8200051352, 820006914<br>91166708, 91168795, 93852699, 93856470, 4430547, 4409210, 4413397, 4414517  |
| <b>DK53.019</b>  | Front right  | Renault Traffic II 4/2001 => 7/2006<br>Renault Traffic II FL 7/2006 => 10/2014  | 4406217, 93866080, 91168794, 91166707, 4414516, 4409208<br>8200051353, 7711135190, 8200169291, 8200069146  |
| <b>DK55.228</b><br><b>DK55.227</b><br><b>IBK55.026</b><br><b>IBK55.018</b><br><b>OBK55.026</b><br><b>OJK55.047</b> | Front left<br>Front right<br>Front left<br>Front right<br>Front left /right<br>Front left /right | Renault Traffic II 2.5 dCi - 9/2002 => 7/2006<br>Opel Vivaro A 2.5 DTI - 5/2001 => 7/2006<br>Opel Vivaro A FL 2.5 DTI - 7/2006 => 10/2014   | 8200485590, 8200169164, 7711135441<br>4411699, 93856471, 4430546, 93850891<br>8200169163, 7711135440<br>93850890, 4411698  |
| <b>DK54.027</b>  | Front left   | Transporter 1.9/2.0/2.4/2.5 - 9/1990 => 5/1996<br>Transporter 1.9/2.0/2.4/2.5 - 1/1996 => 6/2003  | JZW407449FX, 701407449FX, 701407451X, 701407271M   |
| <b>DK54.003</b>  | Front right  | Transporter 1.9/2.0 (7J/7H) - 4/2003 => 11/2009<br>Transporter 1.9/2.0 (7E/7F) - 9/2009 => 8/2015   | 7H0407452X, 7H0407452V, 7H0407452TX, 7H0407452SX, 7H0407452NX, 7H0407452NV,<br>7H0407272S, 7H0407272CH, 7H0407272BK, 7H0407272BC, 7H0407272AJ  |
| <b>DK54.023</b><br><b>DK54.006</b>   | Front left<br>Front right  | Transporter 4/2003 => 11/2009<br>Transporter 9/2009 => 8/2015<br>Transporter 4/2015 => 11/2019  | 7E0407271G, 7E0407271L, 7E0407271P, 7E0407451AX7H0407272BL, 7H0407272T,<br>7H0407452AV, 7H0407452AX, 7H0407 452HX, 7H0407452JV, 7H0407452JX, 7H0407272BD,<br>7H0407 452PX  |
| <b>DK54.039</b><br><b>DK54.010</b>   | Front left<br>Front right  | Multivan VI 2.0 BiTDi 6/2015 =><br>Transporter 2.0 TDi 9/2009 => 8/2015<br>Transporter 2.0 TDi 4/2015 => 11/2019<br>Transporter FL 2.0 TDi 7/2019 =>  | 7H0407271AA, 7H0407271AC, 7H0407271AF, 7H0407271AH, 7H0407271Q, 7H0407451AX,<br>7H0407451DX<br>7H0407452JX, 7H0407452JV, 7H0407452AV, 7E0407452KX, 7E0407272BB   |
| <b>DK51.001</b>  | Front left /right  | Vito 2.14, 3.0, 3.2, 3.5, 3.7 auto 1/2003 => 9/2014<br>Vito Autobus 2.14, 3.0, 3.2, 3.5, 3.7 auto (W639) 6/2004<br>=> 7/2008<br>Viano 2.15, 3.2, 3.0, 3.5, 3.7 auto (639) 1/2003 => 3/2014  | A6393501810, 6393501810  |
| <b>DK51.003</b>  | Front left   | Vito 2.2 CDi (638) 1/1996 => 9/2003   | A6383342334, 6383342334  |
| <b>DK66.005</b><br><b>DK66.012</b>   | Front left<br>Front right  | Fiat Ducato (230-231-232-234) 2/1994 => 12/2001<br>Fiat Ducato (243-244-245-247) 1/2002 => 6/2006<br>Fiat Talento (290) 3/1988 => 12/1994<br>Citroën Jumper II 1/2002 => 6/2006<br>Citroën Relay I 2/1994 => 12/2001<br>Citroën Relay II 1/2002 => 6/2006<br>Peugeot Boxer I 2/1994 => 12/2001<br>Peugeot Boxer II 1/2002 => 6/2006   | 3272CJ, 3272J0, 3272J3, 3272J4, 32726K<br>1491235080, 1495537080, 1463105080, 1473299080, 71783034, 71783035, 71784343,<br>71720919, 71721371<br>32735S1, 3273Q5, 3273CH, 3273CJ<br>71783073, 95569340, 9607411180, 9617303380   |
| <b>DK66.007</b>  | Front left   | Citroën Jumper III 7/2006 => 5/2014<br>Citroën Jumper III FL 3/2014 =><br>Citroën Relay III 7/2006 => 5/2014<br>Citroën Relay III FL 3/2014 =><br>Peugeot Boxer III 7/2006 => 5/2014<br>Peugeot Boxer III FL 3/2014 =><br>Fiat Ducato II (250-251) 7/2006 => 11/2011<br>Fiat Ducato II (250) 6/2014 =><br>Fiat Ducato II (250-251) 5/2011 =><br>Fiat Ducato II Maxi (250) 6/2014 => | 3273PN, 3273PX, 1608509380<br>1369959080   |
| <b>DK66.010</b>  | Front left   | Fiat Ducato (230-231-232-234) 2/1994 => 12/2001<br>Fiat Ducato (243-244-245-247) 1/2002 => 6/2006<br>Fiat Ducato (243-244-245) 1/2008 => 12/2011<br>Citroën Jumper II 1/2002 => 6/2006<br>Citroën Relay II 1/2002 => 6/2006<br>Peugeot Boxer II 1/2002 => 6/2006<br>Peugeot Boxer I 2/1994 => 12/2001   | 1611568380, 3273NC, 3273ZZ, 3273R3, 3273R2, 3273CN, 32735W, 327313, 327309, 3273CP,<br>32735V, 1478552080, 327310<br>51872272, 1495554080, 1487936098, 1491244080, 1487936088  |
| <b>DK66.018</b>  | Front left   | Fiat Scudo II 1/2007 => 7/2016<br>Citroën Jumpy III 1/2007 => 6/2016  | 71792565, 1497187080, 1497187088<br>3272NQ, 3272SF   |
| <b>DK66.008</b>  | Front right  | Citroën Dispatch III 1/2007 => 9/2016<br>Citroën DS5 10/2011 => 5/2015<br>Citroën C5 (X7) 3/2008 => 6/2017<br>Peugeot Expert III 1/2007 => 6/2016<br>Peugeot 508 (W2) 9/2010 => 9/2014<br>Peugeot 508 FL (W2) 8/2014 => 9/2018<br>Peugeot 508 II (R8) 9/2018 =><br>Peugeot 407 4/2004 => 8/2011   | 3273SW, 3273GE, 3273NQ, 3273NP<br>71791561, 1497188088, 1497188080   |
| <b>DK66.014</b>  | Front left   | Citroën Jumpy III 1/2007 => 6/2016<br>Citroën Dispatch III 1/2007 => 9/2016   | 9801611980, 1607947180, 3272NL, 3272NK, 3272XN, 3272XL, 3272VL<br>1440100688, 1497196080, 1497191088, 1497191080, 71792558   |
| <b>DK66.020</b>  | Front right  | Citroën C5 (X7) 3/2008 => 6/2017<br>Peugeot Expert III 1/2007 => 6/2016<br>Fiat Scudo II 1/2007 => 7/2016   | 3273NL, 3273NK, 3273YG, 3273YF, 3273VZ, 3273VY, 1607947080, 9801618880<br>1440100788, 1497197080, 1497192088, 1497192080, 71792555   |
| <b>DK66.011</b>  | Front right  | Fiat Ducato (230-231-232-234) 2/1994 => 12/2001<br>Fiat Ducato (243-244-245-247) 1/2002 => 12/2011<br>Citroën Jumper I 2/1994 => 12/2001<br>Citroën Jumper II 1/2002 => 6/2006<br>Citroën Relay I 2/1994 => 12/2001<br>Citroën Relay II 1/2002 => 6/2006<br>Peugeot Boxer I 2/1994 => 12/2001   | 32735T, 3273Q6, 3273R0, 3273R1, 3273CK, 3273CL<br>1491238080, 1491240080, 1495542080, 1463108080   |

This document is the exclusive property of NTN-SNR ROULEMENTS. Any total or partial reproduction hereof without the prior consent of NTN-SNR ROULEMENTS is strictly prohibited. Legal action may be brought against anyone breaching the terms of this paragraph. NTN-SNR ROULEMENTS shall not be held liable for any errors or omissions that may have crept into this document despite the care taken in drafting it. Due to our policy of continuous research and development, we reserve the right to make changes without notice to all or part of the products and specifications mentioned in this document.  
© NTN-SNR ROULEMENTS, international copyright 2022.

